



## **Condensation Policy**

### **Coburg Basketball Stadium**

Due to the colder weather that has been experienced this winter the condensation issue at Coburg Basketball Stadium has been more of an issue than in previous years. Please note that we are working to remedy this problem and we will have a solution within the next 2 – 4 weeks by means of replacing the skylights with roof sheeting.

During this period can you please take note of the following policy we would like to implement regarding the condensation.

- Please note that this policy will be implemented from Saturday the 22<sup>nd</sup> of July 2017 and will be applicable to the first 2 time slots fixture
- If the temperature is forecasted to drop below 4 degrees overnight the following mornings, the first 2 slots fixture will be cancelled
- The Coburg Basketball Association Administrator will notify all clubs involved by 9pm the Friday night prior to the Saturday morning fixtures
- If clubs have not received notification of games being cancelled by 9pm the Friday evening prior please assume games will progress.

Please note as stated above we are very hopeful that will be a 2 – 4 week policy that needs to be implemented with the replacement of the skylights occurring within this period.

We apologise for the inconvenience and we will do our best to work within the above timeframes.

Kind Regards  
Rod Leonard  
Sports Stadiums Victoria  
Operations Manager